



| Symbol | Dimensions In Millimeters |       | Dimensions In Inches |       |
|--------|---------------------------|-------|----------------------|-------|
|        | Min.                      | Max.  | Min.                 | Max.  |
| A      | 4.800                     | 5.000 | 0.189                | 0.197 |
| B      | 3.800                     | 4.000 | 0.150                | 0.157 |
| C      | 1.300                     | 1.750 | 0.051                | 0.069 |
| D      | 0.300                     | 0.500 | 0.012                | 0.020 |
| F      | 1.000                     |       | 0.039                |       |
| H      | 0.100                     | 0.250 | 0.004                | 0.010 |
| I      | 0.050                     | 0.250 | 0.002                | 0.010 |
| J      | 5.800                     | 6.200 | 0.228                | 0.244 |
| M      | 0.400                     | 1.270 | 0.016                | 0.050 |