




| Symbol | Dimensions In Millimeters |        | Dimensions In Inches |       |
|--------|---------------------------|--------|----------------------|-------|
|        | Min                       | Max    | Min                  | Max   |
| A      | --                        | 2.475  | --                   | 0.097 |
| A1     | 0.000                     | 0.150  | 0.000                | 0.006 |
| A2     | 2.220                     | 2.320  | 0.087                | 0.091 |
| b      | 0.230                     | 0.310  | 0.009                | 0.012 |
| D      | 18.300                    | 18.500 | 0.720                | 0.728 |
| D1     | 8.561                     | 8.761  | 0.337                | 0.345 |
| e      | 0.635                     |        | 0.025                |       |
| E      | 10.100                    | 10.500 | 0.398                | 0.413 |
| E1     | 7.400                     | 7.600  | 0.291                | 0.299 |
| E2     | 5.390                     | 5.590  | 0.212                | 0.220 |
| L      | 0.500                     | 1.000  | 0.020                | 0.039 |
| c      | 0.150                     | 0.190  | 0.006                | 0.007 |