



Symbol	Dimensions In Millimeters		Dimensions In Inches	
	Min	Max	Min	Max
A	0.500	0.600	0.020	0.024
A1	0.000	0.050	0.000	0.002
A3	0.100	0.200	0.004	0.008
D	2.900	3.100	0.114	0.122
E	2.900	3.100	0.114	0.122
b	0.100	0.200	0.004	0.008
b1	0.180	0.280	0.007	0.011
L	0.300	0.500	0.012	0.020
L1	1.350	1.550	0.053	0.061
L2	1.400	1.600	0.055	0.063
L3	2.100	2.300	0.083	0.091
e	0.450		0.018	
e1	0.500		0.020	
e2	1.000		0.039	
e3	0.950		0.037	
e4	0.800		0.031	
K	0.750		0.030	