



| Symbol | Dimensions In Millimeters | | Dimensions In Inches | |
|--------|---------------------------|--------|----------------------|-------|
| | Min. | Max. | Min. | Max. |
| A | 12.598 | 13.005 | 0.496 | 0.512 |
| B | 7.391 | 7.595 | 0.291 | 0.299 |
| C | 2.362 | 2.642 | 0.093 | 0.104 |
| D | 0.330 | 0.508 | 0.013 | 0.020 |
| F | 1.194 | 1.346 | 0.047 | 0.053 |
| H | 0.229 | 0.330 | 0.009 | 0.013 |
| I | 0.102 | 0.305 | 0.004 | 0.012 |
| J | 10.008 | 10.643 | 0.394 | 0.419 |
| M | 0.381 | 1.270 | 0.015 | 0.050 |