



| Symbol | Dimensions In Millimeters | | Dimensions In Inches | |
|--------|---------------------------|-------|----------------------|-------|
| | Min | Max | Min | Max |
| A | 0.800 | 1.000 | 0.031 | 0.039 |
| A1 | 0.000 | 0.050 | 0.000 | 0.002 |
| A3 | 0.175 | 0.250 | 0.007 | 0.010 |
| b | 0.200 | 0.300 | 0.008 | 0.012 |
| b1 | 0.700 | 0.800 | 0.028 | 0.031 |
| D | 2.950 | 3.050 | 0.116 | 0.120 |
| D2 | 2.450 | 2.550 | 0.096 | 0.100 |
| E | 2.950 | 3.050 | 0.116 | 0.120 |
| E2 | 1.450 | 1.550 | 0.057 | 0.061 |
| e | 0.500 | | 0.020 | |
| L | 0.350 | 0.450 | 0.014 | 0.018 |
| L1 | 0.200 | 0.300 | 0.008 | 0.012 |