



| Symbol | Dimensions In Millimeters | | Dimensions In Inches | |
|--------|---------------------------|-------|----------------------|-------|
| | Min. | Max. | Min. | Max. |
| A | 0.500 | 0.600 | 0.020 | 0.024 |
| A1 | 0.170 | 0.230 | 0.007 | 0.009 |
| b | 0.240 | 0.300 | 0.009 | 0.012 |
| D | 3.600 | 3.680 | 0.142 | 0.145 |
| D1 | 3.200 | | 0.126 | |
| E | 2.750 | 2.830 | 0.108 | 0.111 |
| E1 | 2.000 | | 0.079 | |
| e | 0.400 | | 0.016 | |